

Schedule


Sl.No.	Particulars	Quantity
1	Repairing, Rewinding work of Rotary Exciter unit of locomotives. Specifications 420 KWH BHEL make rotary exciter unit (Stator exciter & rotary exciter), insulation -Class 'F', insulation level - 1000 H	01 Job.

Scope of work :-

- 01) Re- insulation cleaning and varnishing of generator connection leads .
- 02) Re- winding work of rotary Exciter.
- 03) Repairing of stator exciter.
- 04) Varnishing work of rotary & stator exciter .
- 05) All testing of exciter body throughout muggger test.
- 06) Good quality insulating material for leads & terminals ends etc. confirmed to relevant ISI specification has to be used by the firm for rewinding of damaged exciter .
- 07) New replacement of old connection leads & lugs with equivalent leads & lugs in re- wound exciter.

Term & conditions :-

1. The repairing work should be guaranteed for 12 Months.
2. The work shall be completed within a month .
3. All the required material for repairing work shall be arranged by the contractor /firm .
4. Ensuring of exciter healthiness checking & testing of proper working with alternator.
5. The work will be done at firms workshop .
6. Old scrap should not be utilized, the repairing work of exciter ,scrap shall be returned to MPPGCL.
7. To & fro transportation will be arrange by the firm.
8. Collection of the exciter from the site will be the firms responsibility.


S.E.(P&W)
ATPS, Chachai,